

# APPLYING A SMALL STICKER OR DECAL

**PrintSolutions**

## 1 Clean the area thoroughly

Clean the area thoroughly with rubbing alcohol or soap and water. Do not use glass or surface cleaners because it will leave a residue behind that will prevent the sticker from adhering well.

## 2 Prepare the sticker for application

Prepare the sticker for application by firmly rubbing a squeegee or credit card across the clear transfer tape. This removes any air bubbles that may have formed and makes the sticker cling to the transfer tape.

## 3 Peel the white paper backing off

Peel the white paper backing off the sticker. If the sticker clings to the backing, slowly replace the paper backing and repeat Step 2.

## 4 Lower the sticker onto the surface

Slowly lower the sticker onto the surface and rub it in place firmly with a squeegee or credit card. For best results, wait 24 hours before moving to the next step.

## 5 Slowly peel the upper transfer tape off

Slowly peel the transfer tape off at an angle to reveal the graphic. Be careful not to pull the sticker off the surface. If sticker pulls away from the surface repeat Step 4.



\*Use a pin to poke any air bubbles in the centre and push the air out through the hole.  
\*The recommended optimum temperature for applying graphics is 70°F. For best results do not apply a sticker in extreme hot or cold temperatures.



You can see this in detail on Youtube: <https://youtu.be/5QlogSF7mGk>